



Setting the Standards for Home Energy Efficiency

Interpretation: Radiant Barrier Grading Requirements – Roof

Designation: 380-2019-008

Approved: April 27, 2020 by RESNET SDC 300

Effective Date: May 26, 2020

Reference:

Standard ANSI/RESNET/ICC 301-2019
Page Number(s): A-9
Sections(s): A-2.3.2.1(1) and A-2.3.2.2(1)
Table(s): _____
Relating to: Grading requirements for Attic Radiant Barriers

Request from:

Name: Sharla Riead, Accurate Rater Network
Affiliation: Rating Quality Assurance Provider
Address: 11601 Orchard Road
City: Kansas City State: MO Zip: 64134
Email: sharla@accuraterater.com

Background Statement: *Provided by person requesting the interpretation.*

The wording pertaining to voids in radiant barrier installation is somewhat confusing because the Grade I and Grade II criteria refer to the roof being bare or bare wood.

Proposed Interpretation: *Provided by person requesting the interpretation.*

The term “roof” in these statements is referring to the attic facing roof decking.

SDC Response:

Is the proposed interpretation correct? Yes No

SDC Comments: